Ship Name: AJAMA Ship Type: Containership

IMO Number: 9003304 Flag: Cyprus

Date Detained: 01/29/2002 Class Society: Germanischer Lloyd

Port: Los Angeles, California Company(s): Owners, Operators or

Peter Dohle Schiffahrts-kg

Deficiencies: Code - Category Description

0950 - Electric equipment in Emergency generator did not automatically

start or take an electrical load during

inspection.

Ship Name: ALKYON Ship Type: Tankship (Not Specified)

IMO Number: 8025472 Flag: Bahamas

Date Detained: 01/17/2002 Class Society: Lloyd's Register of Shipping

Port: New York, New York Company(s): Owners, Operators or

Ionia Management S.A.

Deficiencies: Code - Category Description

0610 - Lifeboats The port lifeboat was not ready for immediate

use.

their assigned duties during the abandon

ship drill.

2020 - Fire drills The crewmembers were unable to perform

their assigned duties during the fire drill.

2545 - Reports/analysis of Procedures to control all documents and data

non-conformities, etc. which are relevant to the Ship's management

system are not established or being

maintained.

Ship Name: BALBOA REEFER Ship Type: Refrigerated Cargo Carrier

IMO Number: 7809687 Flag: Cyprus

Date Detained: 01/14/2002 Class Society: Lloyd's Register of Shipping

Port: Jacksonville, Florida Company(s): Owners, Operators or

Omega Shipping Co. Ltd

International Reefer Services S.A.

Deficiencies: Code - Category Description

0610 - Lifeboats Lifeboat motor inoperative.

Ship Name: HEROS Ship Type: Gas Carrier (Non-Specified)

IMO Number: 7414133 Flag: Norway

Date Detained: 01/07/2002 Class Society: Det Norske Veritas

Port: Big Stone Anchorage, Delaware Company(s): Owners, Operators or

KS/AS Heragas

Solvang ASA

Deficiencies: Code - Category Description

2545 - Reports/analysis of Master failed to report multiple holes with

non-conformities, etc. temporary cement patches iwo sounding tube striker plates in double bottoms via SMS as

required.

2550 - Maintenance of ship and

equipment

Vessel not conducting required maintenance

on deck spray system.

1799 - Other (MARPOL Annex I) Oil record Book incomplete.

2555 - Documentation Master & Chief Offficer hand over notes

required by SMS not performed.

2525 - Masters responsibility and

authority

Master failed to inform Class Society of major structural defects (holes in hull) during class survey in November 2001.

2525 - Masters responsibility and

authority

Master, Chief Officer and Chief Engineer not sufficiently familiar with the vessel's

Safety Management System.

Ship Name: ISMAEL EXPRESS Ship Type: General Dry Cargo Ship

IMO Number: 5411137 Flag: Panama

Date Detained: 01/05/2002 Class Society: Panama Maritime Documentation

Service

Port: Port Canaveral, Florida Company(s): Owners, Operators or

FEDCO World Management Inc.

Deficiencies: Code - Category Description

0420 - Provisions Inadequate food and water for crew.

Ship Name: JULLIETA Ship Type: Bulk Carrier

IMO Number: 8102749 Flag: Malta

Date Detained: 01/31/2002 Class Society: Bureau Veritas

Port: N. Charleston, South Carolina Company(s): Owners, Operators or

Corner Shipping Co.

Elite Shipping Limited

Deficiencies: Code - Category Description

0680 - Embarkation arrangt. Starboard lifeboat motor difficult to start.

survival craft

Lower hand crank sprocket slips and disengages while trying to start motor

Ship Name: MOLAT Ship Type: Bulk Carrier

IMO Number: 7601621 Flag: Saint Vincent and the Grenadines

Date Detained: 01/23/2002 Class Society: Croatian Register of Shipping

Port: Charleston, South Carolina Company(s): Owners, Operators or

Corisles Shipping Co.

Tankerska Plovidba

Deficiencies: Code - Category Description

0950 - Electric equipment in Eight of eleven emergency batteries found

inoperative.

2020 - Fire drills Crewmembers not familiar with their

emergency fire responsibilities

Ship Name: MORILLO Ship Type: Refrigerated Cargo Carrier

IMO Number: 7105031 Flag: Cayman Islands

Date Detained: 01/08/2002 Class Society: Germanischer Lloyd

Port: Pascagoula, Mississippi Company(s): Owners, Operators or

Holy House Shipping

Morillo Shipping Ltd.

Deficiencies: <u>Code - Category</u> <u>Description</u>

0740 - Pumps Primary and emergency fire pumps

Ship Name: ORIENTAL CHILAN Ship Type: Refrigerated Cargo Carrier

IMO Number: 8301723 Flag: Panama

Date Detained: 01/10/2002 Class Society: Indian Register of Shipping

Port: Pago Pago, American Samoa Company(s): Owners, Operators or

Kao Sheng Marine S.A.

Go Rising Trading Ltd

Deficiencies: <u>Code - Category</u> <u>Description</u>

2540 - Emergency preparedness Crew unable to demonstrate proficiency in

fire drill.

Ship Name: ST CLEMENS Ship Type: Tankship (Not Specified)

IMO Number: 9222560 Flag: Singapore

Date Detained: 01/12/2002 Class Society: Nippon Kaiji Kyokai

Port: Port Canaveral, Florida Company(s): Owners, Operators or

Shenlong Maritime

Maruta Industries Co. LTD.

Deficiencies: Code - Category Description

0936 - Steering gear Crewmembers unable to demonstrate

proficiency in operating steering gear.

1050 - Inert gas alarm Operation of inert gas system alarms could

not be verified and crew members were unfamiliar with its operation. Portable 02 instruments were both inoperable, no spares

were available.

Ship Name: STANDARD VIGOR Ship Type: Bulk Carrier

IMO Number: 7928134 Flag: Malta

Date Detained: 01/24/2002 Class Society: Det Norske Veritas

Port: New Orleans, Louisiana Company(s): Owners, Operators or

Standard Vigor Shipping Standard Bulk Tansport Co.

Deficiencies: <u>Code - Category</u> <u>Description</u>

1410 - Propulsion main engine Main engine no. 4 cylinder high-pressure

fuel line ruptured and leaking.

1410 - Propulsion main engine Main engine no. 4 cylinder has excessive

hydraulic oil leaks.

0936 - Steering gear Steering gear relief valve has excessive

hydraulic oil leaks.

0936 - Steering gear no. 1 and no.2 direction

control valves have excessive hydraulic oil

leaks.

0720 - Fire fighting equipment Four engine room fire stations and one fire

station on deck missing fire nozzles.

1440 - Bilge pumping Ballast water suction pipe leaking

excessively at bilge deck located stbd side

engine room.